

APPENDIX B

VAOT BRIDGE INSPECTION REPORT AND INVENTORY

VERMONT BRIDGE INSPECTION REPORT

ROUTE NO. FAS188 BR. NO. 6 DIST. 6 DATE 7-16-92
 TOWN Warren FEATURE CROSSED Mad River
 BRIDGE TYPE Single Span Queen Post Covered Bridge INSPECTOR Arlan W. Elwood

ITEM 58, DECK		*. CRITICAL AREAS
1.	WEARING SURFACE <u>none</u>	
2.	STRUCTURAL CONDITION <u>wear in travel areas of nail laminated untreated timber deck</u>	<u>7</u>
3.	CURBS <u>none</u>	
4.	SIDEWALKS <u>N/A</u>	
5.	RAILING <u>none except wood plank nailed to interior siding</u>	<u>5</u>
6.	DRAINS <u>none</u>	
7.	JOINT LEAKAGE <u>at abut's</u>	<u>5</u>
8.	EXPANSION DEVICE <u>none</u>	
INSPECTORS CONDITION RATING		<u>7</u>

ITEM 59, SUPERSTRUCTURE		
1.	BEARING DEVICES <u>supported on end wood floor beams</u>	<u>6</u>
2.	GIRDERS/BEAMS	
3.	COVER PLATES	
4.	TRUSSES, PORTALS, BRACING, ETC. <u>split, knots & checks in visible portions</u>	<u>5</u>
5.	FLOOR BEAMS <u>large split in one member of eastern interior FB</u>	<u>5</u>
6.	STRINGERS <u>rot in bottom of northernmost interior stringer</u>	<u>5</u>
7.	PAINT <u>N/A</u>	
8.	RUST <u>visible portions of connection bolts quite rusty</u>	<u>5</u>
9.	RIVETS, BOLTS, WELDS	
10.	COLLISION DAMAGE <u>minor scuffing at 2 knee braces</u>	<u>6</u>
11.	ALIGNMENT OF MEMBERS <u>minor sweep in south truss</u>	<u>6</u>
12.	VIBRATIONS, DEF. UNDER LOAD <u>minor vibration under load</u>	<u>6</u>
13.	FCM YES ___ NO ___ COMMENT: _____	
INSPECTORS CONDITION RATING		<u>5</u>

ITEM 60, SUBSTRUCTURE		
1.	ABUTMENT - STEM <u>East abut good - west abut has bare cracking & heavy scaling esp. near butt</u>	<u>5</u>
A.	BACKWALLS <u>good</u>	<u>8</u>
B.	BRIDGE SEATS <u>good</u>	<u>8</u>
C.	WINGS <u>good at east abut, heavy spalling & cracking at west abut</u>	<u>5</u>
D.	FOOTINGS	
E.	PILES	
F.	EROSION <u>scour at both abutments but no undermining</u>	<u>5</u>
G.	SETTLEMENT	
2.	PIERS - CAPS <u>N/A</u>	
A.	COLUMNS	
B.	FOOTINGS	
C.	SCOUR	
D.	SETTLEMENT	
E.	PILES	
INSPECTORS CONDITION RATING		<u>5</u>

7/16/92

This structure is a single span ^{Queen}~~elcan~~ post covered bridge. The decking on this structure is a nail laminated untreated timber. There is bituminous concrete pavement in both approaches to the structure. Bituminous concrete pavement in the west approach is in poor condition. There is potholing and raveling at the shoulders. Bituminous concrete pavement in the east approach has areas of longitudinal and transverse cracking. Approach railing at the east approach is standard steel beam on light steel posts without offset blocks. The timber deck is in fair condition. There is some minor gouging at various locations and some tire tread wear through the traffic portions of this deck. There are concrete backwalls at each end of the structure. These backwalls are in good condition. The roof is covered with cedar shingles. There are random holes in these shingles that should be repaired. The upper portion of the truss lateral bracing and knee bracing members that are visible are in fair condition. There is some splitting but no apparent rot. The lower portions of the trusses ^{are} the top of the bottom chord is not visible due to the boarding. The alignment of the members in the structure remains good with no apparent sweeps or sagging. The floor system consists of longitudinal stringers spanning between floor beams at the abut. and floor beams at the third points of the span. Visible portions of the bottom chord have horizontal splitting but no apparent rot. The floor beams have areas of splitting and checking but no apparent rot. The interior floor beams are made up of three beams bolted together, one of these beams on the eastern interior floor beam has a split for 3/4 of its length. The visible portions of the bolted connections are quite rusty. The northern most stringer spanning between the two middle floor beams has areas of checking and apparent rot in the bottom of it. However, this condition appears only in the bottom of this stringer. The remaining stringers have areas of splitting and no apparent rot. The east abut. and wingwalls are new since the last inspection and are in good condition. The west abut. is a concrete facing on a laid up stone. The south wingwall has areas of heavy spalling as does the abut. end of the north wingwall. The abut. itself has horizontal cracking and heavy scaling particularly down near the flow line. There is also cracking with leakage in the north wingwall. There is some scour along each abut. but no undermining at this time. There is a gravel bar upstream of the structure. There is stone fill along the west bank upstream of the structure. There is an old log crib retaining wall on the east side of the channel downstream of the structure. Overall the channel is in good condition. This structure is not posted for a weight limit but is limited to car traffic only with signs saying "No Trucks or Buses".

onsys717.awe

Elwood

Run Date 02/16/94 Vermont Agency of Transportation Rte. No. FAS 0188
 Rev. By _____ RIS, Print Items for Revision Bridge No. 00006
 Rec. No. 1556 State Structures 20 Feet And Over Town WARREN
 Rt. Log 00006 000058' Bridge District 6
 Cross Ref. _____

1. State Code 501
 2. District 6
 3. County Code 023
 4. Place Code 76525
 5. Inventory Route 141000030
 6. Name of Feature Crossed MAD RIVER
 7. Facility Carried by TR 03 FAS 188
 8. Bridge Code Number 200188000612172
 9. Location 0.5 MI E JCT. VT.100 S
 10. Inv. Route, Min. Vertical Clearance 1110
 11. Milepoint 003970
 16. Latitude 44067
 17. Longitude 072514
 19. Distance to Alternate Facility, Miles 01
 20. Toll 3
 21. Maintenance Responsibility 03
 22. Owner 03
 26. Functional Classification Code 07
 27. Year Structure was Built 1879
 106. Year Reconstructed 0000
 208. Last Project Number COV. BR.
 209. Project Name
 28. Lanes On/Under Structure 0100
 29. ADT On Structure 000250
 30. Year Of ADT 91
 242. Source of ADT 2
 31. Design Live Load 0
 32. Approach Width (Incl. Shoulder), Feet 021
 33. Bridge Median 0
 34. Skew Angle, Degrees 00
 35. Structure Flared 0
 36. Traffic Safety Features 0000
 37. Historical Significance 1
 38. Navigation Control? 0
 39. Nav. Vertical Clearance, Feet 000
 40. Nav. Horizontal Clearance, Feet 0000
 41. Structure Open, Posted or Closed to Traffic F
 42. Type of Service 15
 43. Type of Structure, Main Spans 710
 44. Type of Structure, Approach Spans 000
 45. Number of Main Spans 001
 46. Number of Approach Spans 0000
 47. Total Horizontal Clearance, Feet 139
 48. Maximum Span Length, Feet 0047

