

Warren Historical Society—Blair Barn Restoration



Pre-Construction June 2012



Jacking up the Barn

New floor beam installed



Getting ready for new perimeter sills

Warren Historical Society—Blair Barn Restoration



New perimeter sills installed, cribbing removed, ready to rotate to new location



All set to rotate to new location

Warren Historical Society—Blair Barn Restoration



Barn relocated, cribbing back in...getting ready for new foundation



Warren Historical Society—Blair Barn Restoration



Concrete forms in for new foundation



Foundation poured—concrete forms off



Barn on new foundation—ready for new concrete floor

Warren Historical Society—Blair Barn Restoration



Getting ready for new concrete floor



New Concrete floor pored



Phase I Complete...Warren's historic hearse returns to the Barn...

